U.S. Naval Hospital, Incinerator Building (Bldg.13) Park Boulevard, Balboa Park San Diego San Diego County California

HABS CAL, 37-SANDI, 21-M-

HABS No. CA-1548-M

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Western Region
Department of the Interior
San Francisco, CA 94102

Form 10-920 (June 1983)

UNITEO STATES OEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS CAL. 37-SABIG. 13

HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM

STATE:	COUNTY:	TOWN OR VICINITY:
California	San Diego	City of San Diego
HISTORIC NAME OF STRUCTURE	(SOURCE IN PARENTHESES):	U.S. Naval Hospital, HABS NO.:
Incinerator Building		
(Original name in construction of Naval Hospital Complex)		
SECONDARY OR COMMON NAME OF STRUCTURE: U.S. Naval Hospital,		
Building 13.		
ADDRESS: U.S. Naval Hospital, Balboa Park, San Diego, CA, 92134		
The Hospital complex is on the south side of Park Boulevard.		
This building is between Wieber and Farenholt Avenues.		
OATE OF CONSTRUCTION:		: U.S. Navy Bureau of Yards and Docks
1924 (Construction Drawing		ned Kandel, Menzies, and Lamont)
		arrative for discussion of designers.
ARCHITECTURAL AND HISTORICAL SIGNIFICANCE (ORIGINAL USE OF STRUCTURE IN PARENTHESES):		
A contributing structure in an eligible historic district. Not individually significant.		
(Oesigned and built to be an enclosure for an incinerator.)		
STYLE: Utilitarian.	TEME: Deinferen I consu	L. Cl 1-11
MATERIAL AND STRUCTURAL SYSTEMS: Reinforced concrete floors, hollow-tile walls, stucco		
exterior, wood roof framing, and built-up composition roofing.		
SHAPE AND DIMENSIONS OF STRUCTURE: Rectangular		
EXTERIOR FEATURES OF NOTE: (PLEASE SEE 1985 PHOTOGRAPHS.) First floor walls are		
reinforced concrete, second floor walls are tile block.		
INTERIOR FEATURES OF NOTE:	None	
	None.	
MAJOR ALTERATIONS AND ADDITIONS WITH DATES:		
1 Building 19 built contiguous to this Building 13 in 1927. Converted to office use at		
later date.		
Í		
PRESENT CONDITION AND USE: Adequately maintained with no eye to historic preservation.		
Exterior has had only minor changes. Upstairs is conference room. Basement is wax		
issue.		
AOOITIONAL INFORMATION: This Building 13 is merged with Buildings 12 and 19. Site		
slopes east.		
LCOURCE OF THEODIATION		2
SOURCES OF INFORMATION: Original construction drawings; Architectural and Historical Resources Survey by Sally Woodbridge; and, field inspection.		
COMPILER, AFFILIATION: JOE	l Sharp, employee of Rob	ert O. Ferris, OATE:
A.I.A., Contractor to Oept	. of the Navy, Western D	
Facilities Engineering Com		·
. 		

